Lathe, Tools, Snail, Laying Out, Striking Trains, 299, Eight-day Snail Strike, Electric Chimes, Clocks, Synchronizing, 400, Synodic Month, T Table, Lengths of Pendulums

by Robert Kelley, Walter Sawyer, Amado Beard

Lathe, Tools, Snail, Laying Out, Striking Trains, 299, Eight-day Snail Strike, Electric Chimes, Clocks, Synchronizing, 400, Synodic Month, T Table, Lengths of Pendulums. Vibrations Length of bob 10.5 Weight of Lead, Zinc and Cast Iron Cylinders One-Half Inch Long. ---------- Weight in Pounds. Diameter ---------- in Inches. Lead Zinc Iron ---------- .25 .020 .012 .012 .5 .080 .049 .050 .75 .180 .111 .114 1. .321 .198 .204 1.25 .503 .310 .319 1.5 .724 .447 .459 1.75 .984 .607 .624 2. 1.287 .794 .816 2.25 1.630 1.005 1.033 2.5 2.009 2.239 1.274 2.75 2.434 1.502 1.544 3. 2.897 1.788 1.837 3.25 3.400 2.098 2.156 3.5 3.944 2.434 2.491 3.75 4.51 2.783 2.865 4.